Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-820132
Estimate date:	9 May 2024
Customer:	Cassandra Herrera
Phone:	281-555-4575
Insurance claim:	C-1213
Vehicle:	2018 Ford F-150
VIN:	54W3HD5226PZW5503
License plate:	067 BMN

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,683.38
Hood panel	1	$1,624.45
Right front door shell	1	$1,248.29
Body labor	46.0 hrs	$3,126.30
Paint and materials		$1,466.70
TOTAL		$9,149.12

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including the bumper cover, hood leading edge, and both headlamp assemblies. Crush pattern and paint transfer line up with the described contact, and nothing observed points to a different event. The repair plan calls for replacing the bumper cover and headlamps, refinishing the hood, and checking the radiator support and cooling components for hidden damage before final sign-off. The labor hours listed fit the scope of this damage. The invoices submitted show no repeated charges for the same operations. No earlier damage to this vehicle is known from prior records or the owner's account.