Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-859463
Estimate date:	August 20, 2024
Customer:	Jacob Hernandez
Phone:	281-555-9592
Insurance claim:	C-1214
Vehicle:	2021 Honda Civic
VIN:	7H42Z8AV0VK5M1922
License plate:	5IT E43

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$269.69
Left front fender	1	$273.31
Headlamp assembly	1	$185.72
Body labor	21.1 hrs	$465.00
Paint and materials		$223.94
TOTAL		$1,417.66

Appraiser remarks

The vehicle shows heavy crush and scraping along the driver side, with the rear quarter panel and two door panels bent inward and the side glass cracked. Some of the lower rocker damage may not be from this impact, and I could not confirm that from the photos alone. Billing records show no repeated charges. The labor hours requested are far aobve what this damage calls for, roughly three times a typical estimate for this work, so I recommend a line-by-line review. No prior damage to this vehicle is on file. Plan: straighten panels, replace the cracked glass, and refinish the affected sections, with the quetsioned rocker repair held pending a re-inspection.