Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-331497
Estimate date:	27 Jan 2023
Customer:	Toni Richardson
Phone:	281-555-1719
Insurance claim:	C-1216
Vehicle:	2021 Honda Civic
VIN:	U09AWV9U73AR21054
License plate:	

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,399.22
Rear bumper cover	1	$1,340.17
Left tail lamp assembly	1	$1,036.11
Body labor	47.4 hrs	$3,220.88
Paint and materials		$1,823.59
TOTAL		$8,819.97

Appraiser remarks

Rear bumper cover cracked and displaced, trunk lid edge deformed, and the left tail lamp assembly broken. The damage pattern is largely consistent with the reported impact direction and force. Several older scratches sit near the rear quaretr panel and may predate this loss; they are noted separately and are not included in the repair scope. Labor horus for removal, replacement, and refinishing of the bumper, lid, and lamp fit the documented damage. Two similar charges submitted on the same day are under review before the estimate is finalized. Repair plan: replace bumper cover, align and repair trunk lid, install new tail lamp, refinish affected panels, and recheck mounting points after parts are fitted.