Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-284770
Estimate date:	10/21/2023
Customer:	Megan Gutierrez
Phone:	346-555-5585
Insurance claim:	C-1217
Vehicle:	2018 Hyundai Elantra
VIN:	C2X2W73J925N48786
License plate:	YUZ3345

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,409.58
Left front fender	1	$943.13
Hood panel	1	$610.17
Body labor	33.6 hrs	$2,285.12
Paint and materials		$1,001.83
TOTAL		$6,249.83

Appraiser remarks

Left rear quarter panel and rear door show crumpling consistent with a side impact at an intersection, with deformation tracking from the door seam back toward the wheel well. Structural measurements taken on the frame rail confirm the force path described in the claim. Repair plan calls for replacing the rear door shell, straightening the quarter panel, and refinishing adjacent panels for color match. The labor hours submitted line up with the extent of the damage seen. Invoices from the facility show single entries with no duplicated charges. Nothing in our records or the owner's account points to earlier damage on this area of the vehicle.