Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-865983
Estimate date:	February 25, 2023
Customer:	Leslie Sanchez
Phone:	346-555-9326
Insurance claim:	C-1218
Vehicle:	2014 Hyundai Elantra
VIN:	U9VFXXXR5EKX85402
License plate:	7DG 402

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$793.63
Headlamp assembly	1	$510.59
Front bumper cover	1	$406.85
Body labor	20.0 hrs	$1,357.80
Paint and materials		$755.71
TOTAL		$3,824.58

Appraiser remarks

The vehicle presents with scraping and deep scuffing along the driver-side rear quarter panel, a cracked rear bumper cover at the wheel arch, and a dented rear door skin that runs toward the seam. The pattern of contact is largely consistent with a sideswipe during a lane change, and the transfer marks line up with the reported path of impact. Repair will proceed by blending and refinishing the quarter panel, replacing the bumper cover, and pulling the door dent before paint. The labor hours reqeusted fit the scope of this work, and the parts and charges on the invoice show no repeated entries. Nothing in the vehicle's history suggests earlier damage to these areas.