Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-473074
Estimate date:	2-2-24
Customer:	Linda Lewis
Phone:	346-555-0558
Insurance claim:	C-1219
Vehicle:	2014 Chevrolet Malibu
VIN:	
License plate:	NQQ-6989

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$647.30
Headlamp assembly	1	$555.79
Front bumper cover	1	$325.83
Body labor	17.1 hrs	$1,161.04
Paint and materials		$621.71
TOTAL		$3,311.67

Appraiser remarks

The insured vehicle shows scraping and deformation along the right rear quarter panel, with a cracked taillight lens and a bent rear door frame edge. The damage pattern lines up with a sideswipe from a vehicle moving alongside during a lane change, and the marks run in a consistent direction. Repair will involve replacing the taillight assembly, straightening and refinishing the door skin, and blending paint into the adjacent panel. The labor hours requested are in line with the work described. Shop invioces list each operation once, with no duplicated line items. No prior damage to this area has been reported or fonud in inspection.