Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-739617
Estimate date:	4-16-23
Customer:	Julia Price
Phone:	713-555-2867
Insurance claim:	C-1220
Vehicle:	2021 Kia Sorento
VIN:	V3W7SV6H60MWP8957
License plate:	KGK 298

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$350.96
Trunk lid	1	$403.59
Right tail lamp assembly	1	$288.08
Body labor	13.0 hrs	$882.25
Paint and materials		$353.56
TOTAL		$2,278.44

Appraiser remarks

The rear bumper cover is cracked and displaced, with the trunk lid edge and both tail lamp assemblies showing impact deformation consistent with a straight rear strike. Damage to the left quarter panel and the rear crossmember is limited and follows the same load path, which fits the account given at intake. Labor hours and parts listed on the estimate are reasonable for this scope of repair, and the line items show no duplicated charges. Nothing observed suggests earlier damage to this vehicle. Proposed plan: replace the bumper cover, both tail lamps, and the trunk lid edge trim, repair the quarter panel, and perform a rear alignment check before refinishing.