Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-554390
Estimate date:	5-1-24
Customer:	Cynthia Gordon
Phone:	713-555-7981
Insurance claim:	C-1221
Vehicle:	2012 Honda Civic
VIN:	BHVGDM4U34DZX9782
License plate:	D38 2EA

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,701.37
Rear bumper reinforcement	1	$1,483.71
Rear body panel	1	$815.36
Body labor	43.4 hrs	$2,951.32
Paint and materials		$1,317.39
TOTAL		$8,269.15

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is broken, with the trunk lid showing a crease along its lower edge. The pattern and location of the crush are consistent with the rear-end impact reported, and nothing observed suggests a separate or older event. Repairs proceed by replacing the bumper cover and tail lamp, repairing the trunk lid, and refinishing the affected panels. The labor hours listed are in line with the work required for this damage. No prior damage to this vehicle is known to us, and the invoices submitted contain no duplicated line items.