Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-508250
Estimate date:	28 Jan 2024
Customer:	Brad Rodriguez
Phone:	713-555-1076
Insurance claim:	C-1224
Vehicle:	2020 Hyundai Elantra
VIN:	457FR5Y3XNK790048
License plate:	MVI 810

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,053.88
Rear bumper cover	1	$894.18
Right tail lamp assembly	1	$926.98
Body labor	29.9 hrs	$2,030.80
Paint and materials		$1,217.52
TOTAL		$6,123.36

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease along its lower edge, with the tail lamp assembly broken on the driver's side. Crush and paint transfer on the rear panels line up with the reported impact, and the damage pattern reads as one event. The repair plan calls for replacing the bumper cover and tail lamp, straightening the trunk lid, and refinishing the affected panels. The labor hours we have listed fit the scope of this work. Nothing in the file points to earlier damage on this vehicle, and the invocies we reviewed show no repeated charges for the same operations.