Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-733638
Estimate date:	7 May 2024
Customer:	Sandra Wright
Phone:	346-555-7686
Insurance claim:	C-1225
Vehicle:	2017 Hyundai Elantra
VIN:	P1HA5UES3B62Z2577
License plate:	LOJ 105

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$2,024.93
Left quarter panel	1	$1,778.45
Front bumper cover	1	$979.65
Body labor	62.8 hrs	$3,013.03
Paint and materials		$1,387.47
TOTAL		$9,183.53

Appraiser remarks

The left rear quarter panel and rear door on the insured vehicle show crushed metal, a torn seam along the lower sill, and a cracked taillight housing, which fits the side impact described at the intersection. Paint transfer and the direction of deformation are consistent with the account. Repair plan: replace the rear door shell, straighten and refinish the quarter panel, and replace the taillight assembly. Labor hours run slightly above typical for this level of damage and should be reviewed line by line. Shop records show a single set of charges with no repeated billing. No prior damage to this vehicle is known.