Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-441164
Estimate date:	9-15-24
Customer:	Dawn Matthews
Phone:	346-555-7925
Insurance claim:	C-1226
Vehicle:	2020 Jeep Cherokee
VIN:	X29U4KWS6VBNS9799
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$616.17
Hood panel	1	$518.02
Headlamp assembly	1	$687.62
Body labor	23.5 hrs	$1,601.14
Paint and materials		$884.26
TOTAL		$4,307.21

Appraiser remarks

Vehicle was struck on the front driver-side corner during a left turn. The damage is consistent with the impact described, with a broken headlamp assembly, a cracked bumper cover, and a bent front fender bracket. No prior damage to this vehicle is known, and nothing observed suggests otherwise. The proposed repair plan covers replacing the lamp and cover, straightening and refinishing the fender area, and a wheel alignment check. The labor hours requested fit the extent of the visible damage, and the parts and charges on the invoices show no repeated entries. Repair is recommended as presented.