Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-960897
Estimate date:	29 Sep 2023
Customer:	Michael Wells
Phone:	281-555-5030
Insurance claim:	C-1227
Vehicle:	2016 Toyota Camry
VIN:	J09PEF9DXD8T58143
License plate:	XT4 V4P

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$273.66
Headlamp assembly	1	$249.34
Left quarter panel	1	$315.94
Body labor	8.5 hrs	$579.65
Paint and materials		$275.90
TOTAL		$1,694.49

Appraiser remarks

The vehicle presents with a crushed front bumper cover, a cracked right headlamp assembly, and a bent hood latch support, consistent with a frontal impact during a left turn. Some of the lower radiator support damage may have resulted from this event, though it is not clearly separable from the impact at hand. The repair plan calls for replacing the bumper cover and headlamp, straightening the latch support, and refinishing the affected panels. The labor hours submitted fit the scope of the visible damage, and the parts and charges listed appear once each with no repeated entries. No prior damage to this vehicle is known from the file or the inspection.