Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-642499
Estimate date:	14 Jul 2023
Customer:	Karen Carrillo
Phone:	832-555-0476
Insurance claim:	C-1228
Vehicle:	2017 Chevrolet Malibu
VIN:	JVWJTVJP977LT2733
License plate:	3545 JD

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,376.78
Left tail lamp assembly	1	$1,042.88
Trunk lid	1	$673.66
Body labor	32.0 hrs	$2,173.69
Paint and materials		$1,080.91
TOTAL		$6,347.92

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp assembly is broken, with the trunk lid edge pushed inward. The crush pattern lines up with the impact described, and the damage sits where a rear-end strike would place it. Nothing on the vehicle suggests earlier harm, and no prior repair records have come to light. The shop's plan is to replace the bumper cover and lamp assembly, repair the trunk lid, and refinish the affected panels. The labor huors submitted fit the work required, and the line items show no duplicated charges. Approval of the estimate as written is recommended.