Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-175549
Estimate date:	01/15/2025
Customer:	Erik Ayers
Phone:	832-555-6814
Insurance claim:	C-1230
Vehicle:	2020 Hyundai Elantra
VIN:	K9WFCX495R3KX1461
License plate:	9CB E65

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$283.33
Front bumper cover	1	$265.85
Headlamp assembly	1	$294.95
Body labor	10.6 hrs	$722.70
Paint and materials		$313.84
TOTAL		$1,880.67

Appraiser remarks

Inspection of the front end shows damage consistent with the reported low-speed head-on impact, including the bumper cover, hood leading edge, and radiator support brackets. The pattern and height of the contact points line up with the account given. No earlier damage to the vehicle is known to us, and no prior repair records were found in the file. The labor hours requested fit the extent of the work needed to restore the front structure and replace the affected parts. Two similar charges submitted on the same day are currently being checked against the shop's invoices before payment is considered. Repair is recommended as outlined in the attached parts and labor plan.