Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-891173
Estimate date:	2024-05-01
Customer:	Pamela Edwards
Phone:	281-555-3797
Insurance claim:	C-1232
Vehicle:	2012 Hyundai Elantra
VIN:	BRTSR22X0F4249565
License plate:	

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,305.07
Hood panel	1	$1,140.35
Left front fender	1	$900.78
Body labor	37.9 hrs	$2,575.24
Paint and materials		$1,505.16
TOTAL		$7,426.60

Appraiser remarks

The vehicle arrived with a rear quarter impact on the driver side, consistent with the account of being struck while turning left. Most of the damage lines up with that direction of force, including the bumper cover, rear panel, and tail lamp bracket. A few older scratches along the lower door edge may predate this loss and have been noted separately. The repair plan replaces the damaged bumper cover and rear panel section, with refinishing and a light tail lamp reinstall. The labor hours requested fit the scope of the damage, and the parts and charges on the bill show no repeated entries.