Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-299657
Estimate date:	January 3, 2025
Customer:	Jennifer Johnson
Phone:	346-555-1648
Insurance claim:	C-1234
Vehicle:	2010 Kia Sorento
VIN:	ZM5RWTPN6RTVS9991
License plate:	FEG-6449

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$602.06
Hood panel	1	$342.80
Front bumper cover	1	$371.49
Body labor	12.2 hrs	$828.16
Paint and materials		$444.87
TOTAL		$2,589.38

Appraiser remarks

The vehicle shows front-end damage consistent with a head-on impact at low speed. The bumper cover, grille, hood leading edge and both headlamp assemblies are cracked or displaced, and the radiator support shows a minor bend. Nothing observed suggests earlier damage to this vehicle, and the pattern of deformation matches the account given. The repair plan calls for replacing the bumper cover and lamps, straightening the support, and refinishing the hood and fascia. The labor hours listed fit the work described. Two similar charges posted on the same day are still being reviewed against the parts and labor lines before this estimate is finalized.