Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-539795
Estimate date:	04/17/2023
Customer:	Danielle Hahn
Phone:	832-555-8706
Insurance claim:	C-1235
Vehicle:	2020 Jeep Cherokee
VIN:	T003S9GM8KNW88028
License plate:	NSV-198

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,029.31
Right front door shell	1	$683.57
Headlamp assembly	1	$662.93
Body labor	26.2 hrs	$1,779.74
Paint and materials		$634.60
TOTAL		$4,790.15

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support shows crush consistent with a frontal strike of modest speed. The hood latch and both headlamp assemblies are displaced, and the grille has separated at one clip. The labor hours listed fit the scope of the replacement and refinishing called for here. A few older scratches along the lower driver-side door appear weathered and may predate this loss, so they are noted separately and not included in this repair plan. Two similar parts charges submitted on the same day are being reviewed against the parts invoices before payment is released. Recommend approval of the repair plan as written, pending that review.