# Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-882960 |
| **Estimate date:** | 2-22-24 |
| **Customer:** | Kenneth Joseph |
| **Phone:** | 281-555-1461 |
| **Insurance claim:** | C-1237 |
| **Vehicle:** | 2020 Ford F-150 |
| **VIN:** | YW2CPGWUXVYL56307 |
| **License plate:** | A65 1SA |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Headlamp assembly | 1 | $601.15 |
| Right front door shell | 1 | $527.72 |
| Left quarter panel | 1 | $360.39 |
| Body labor | 14.6 hrs | $992.23 |
| Paint and materials | | $495.58 |
| TOTAL | | $2,977.07 |

### Appraiser remarks

Rear bumper cover cracked at the driver side mount, with the tail lamp housing displaced and the quarter panel showing a creased dent. The repair plan calls for replacing the bumper cover, refinishing the quarter panel, and reinstalling the tail lamp assembly. Labor hours are consistent with the visible damage and the job scope. Billing lines reviewed show no duplicated or repeated charges. A dented area on the quarter panel also appears in an inspection photo taken before this collision, so it is unclear whether all of the listed damage resulted from this impact. The estimate should be reviewed with that prior condition in mind before final approval.