Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-994926
Estimate date:	28 Dec 2024
Customer:	Sarah Carr
Phone:	713-555-2726
Insurance claim:	C-1238
Vehicle:	2012 Toyota Camry
VIN:	1BN356KV04NPL4729
License plate:	3P 9049Q

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,055.81
Left front fender	1	$853.64
Left quarter panel	1	$577.13
Body labor	25.6 hrs	$1,738.49
Paint and materials		$983.27
TOTAL		$5,208.34

Appraiser remarks

The vehicle shows damage consistent with a side impact on the front driver's side while making a left turn. The front bumper cover, left headlamp assembly, and fender are cracked or displaced, with secondary damage to the hood latch area and a bent support bracket. Most of the marks line up with the reported collision path. The repair plan calls for replacing the bumper cover, headlamp, and fender, straightening the bracket, and refinishing the affected panels. Submitted invoices show no duplicated line items, and the labor hours requested match the scope of the work. No prior damage to this vehicle is on record.