Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-145734
Estimate date:	4 Jun 2024
Customer:	Ryan Roberts
Phone:	713-555-5690
Insurance claim:	C-1239
Vehicle:	2024 Kia Sorento
VIN:	CAE5RW863FFSX0802
License plate:	

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$568.41
Left tail lamp assembly	1	$456.35
Trunk lid	1	$487.19
Body labor	17.7 hrs	$1,201.59
Paint and materials		$542.76
TOTAL		$3,256.30

Appraiser remarks

The rear bumper cover is cracked across its center and the right taillight assembly is broken, with scuffing and a bent reinforcement bar behind the cover. This daamge lines up with the impact as it was described, and the pattern of crush and transfer shows no sign of a separate event. No earlier damage to the vehicle is known from our records or from the inspection itself. The invoices submitted contain no repeated charges, and the labor hours requested fit the scope of the repair: replace the bumper cover, reinforcement bar, and taillight, then refinish and recalibrate the parking sensors. I recommend approval of the estimate as presented.