Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-765229
Estimate date:	01/13/2024
Customer:	Meghan Adams
Phone:	
Insurance claim:	C-1241
Vehicle:	2017 Kia Sorento
VIN:	KYUTNLYY2TP4S0518
License plate:	96X 451

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$734.23
Right front door shell	1	$451.86
Headlamp assembly	1	$420.15
Body labor	20.4 hrs	$979.85
Paint and materials		$742.42
TOTAL		$3,328.51

Appraiser remarks

The vehicle shows front quarter panel and bumper damage on the driver's side, with the headlamp assembly cracked and the fender bent inward near the wheel well. The damage pattern is consistent with the impact described in the claim, with contact at the front corner as the vehicle was turning left. Parts and labor figures on the submitted invoices do not repeat any charges. Labor hours appear slightly high for this scope of work and may be reviewed with the shop. No prior damage to the vehicle is known. Recommended plan: replace the headlamp, repair and refinish the fender and bumper cover, and perform a wheel alignment check.