Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-631833
Estimate date:	April 10, 2025
Customer:	Jonathan Cox
Phone:	346-555-3329
Insurance claim:	C-1243
Vehicle:	2021 Honda Civic
VIN:	MXDGGCNU2ZH6F3375
License plate:	870 XPW

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,689.80
Left tail lamp assembly	1	$1,535.97
Rear bumper reinforcement	1	$716.53
Body labor	33.5 hrs	$2,281.10
Paint and materials		$1,523.46
TOTAL		$7,746.86

Appraiser remarks

The rear bumper cover is cracked and the trunk lid edge is bent, with the taillight assembly broken on the driver side. The damage pattern matches the rear-end impact as reported, and nothing points to older damage on this vehicle. The plan is to replace the bumper cover and taillight, straighten and refinish the trunk lid edge, and recheck the rear crush zone once the cover is off. The labor hours fit the work described, and the parts list and invoices show no duplicated charges.