# Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-985709 |
| **Estimate date:** | 06/30/2023 |
| **Customer:** | Heather Curtis |
| **Phone:** | 832-555-5875 |
| **Insurance claim:** | C-1244 |
| **Vehicle:** | 2011 Jeep Cherokee |
| **VIN:** | AM6YEEFN9ZAA48136 |
| **License plate:** | |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Right tail lamp assembly | 1 | $586.75 |
| Trunk lid | 1 | $530.78 |
| Rear body panel | 1 | $434.18 |
| Body labor | 14.8 hrs | $1,004.19 |
| Paint and materials | | $655.63 |
| TOTAL | | $3,211.53 |

### Appraiser remarks

The rear bumper cover is cracked across its center and the trunk lid shows a crease near the latch, with the taillight housing displaced on the driver's side. The pattern and height of this damage line up well with the impact that was reported, and nothing in the inspection points to older or unrelated harm. The labor hours on the estimate are in line with what these repairs typically take. The repair plan calls for replacing the bumper cover and taillight assembly, pulling and refinishing the trunk lid, and checking the rear reinforcement for hidden deformation before final sign-off. Invoices submitted so far show no duplicated charges, and the vehicle's history contains no prior damage to this area.