Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-521421
Estimate date:	12-29-24
Customer:	Lisa Patterson
Phone:	281-555-4911
Insurance claim:	C-1245
Vehicle:	2021 Chevrolet Malibu
VIN:	G1GRL7JK2YK5J4465
License plate:	888 FKE

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,904.41
Right front door shell	1	$1,482.88
Hood panel	1	$1,190.25
Body labor	64.4 hrs	$3,090.76
Paint and materials		$1,272.07
TOTAL		$8,940.37

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support is bent, with the hood latch and both headlamp assebmlies damaged. The crush pattern and paint transfer line up with the reported head-on contact, and nothing I found suggests earlier damage to this vehicle. The proposed plan replaces the bumper cover, radiator support, and lamp assemblies and repairs the hood latch area. The invoices show no repeated charges. Labor hours run a little high for this scope, so I have asked the shop to justify the time on the radiator support and alignment entries before final approval.