Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-327273
Estimate date:	December 16, 2024
Customer:	Justin Stuart
Phone:	713-555-6698
Insurance claim:	C-1246
Vehicle:	2011 Kia Sorento
VIN:	BT9L53KH43P5M6173
License plate:	2H 09673

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,236.64
Rear bumper cover	1	$1,101.11
Right tail lamp assembly	1	$818.78
Body labor	29.4 hrs	$2,002.28
Paint and materials		$1,355.61
TOTAL		$6,514.42

Appraiser remarks

The rear bumper cover is cracked across the center and the tail lamp assembly on the driver side is broken, with the trunk lid showing a crease and misaligned panel gaps. The pattern of crushing and paint transfer on the rear structure matches the impact as it was described. Repairs planned include replacing the bumper cover and lamp, pulling and refinishing the trunk lid, and recalibrating the parking sensors. The labor hours requested fit the extent of the damage, and the invoices show no repeated charges for the same operation. No prior damage to this vehicle is known to us, so the estimate is recommended for approval as submitted.