Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-592872
Estimate date:	5 Mar 2024
Customer:	Charles Johnson
Phone:	713-555-4311
Insurance claim:	C-1248
Vehicle:	2016 Hyundai Elantra
VIN:	B3VR5N0D7YZN71197
License plate:	LB0 D0R

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,224.80
Left front fender	1	$1,270.47
Front bumper cover	1	$744.02
Body labor	51.3 hrs	$2,464.55
Paint and materials		$1,099.55
TOTAL		$6,803.39

Appraiser remarks

The rear bumper cover on the vehicle is cracked and the left taillight assembly is broken, with scuffing along the rear quarter panel that lines up well with the reported impact in the parking lot. Nothing seen so far points to older damage, and no prior repairs are known on this vehicle. The plan is to replace the bumper cover and taillight, refinish the quarter panel, and check the rear sensor bracket once the cover is off. Two similar charges posted on the same day are still being reviewed before payment. The labor hours look somewhat generous for this scope of work and are being checked against standard repair times.