Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-809583
Estimate date:	2023-05-14
Customer:	Brenda Christian
Phone:	281-555-0967
Insurance claim:	C-1249
Vehicle:	2018 Ford F-150
VIN:	67LHBG161W4T25043
License plate:	558 HKQ

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,275.12
Right front door shell	1	$1,130.42
Left quarter panel	1	$789.64
Body labor	36.1 hrs	$2,456.84
Paint and materials		$1,211.68
TOTAL		$6,863.70

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support is bent, with the hood latch and both headlamp assemblies broken away from their mounts. The damage pattern lines up well with a frontal impact at low speed, and nothing I found points to odler damage on the vehicle. The repair plan calls for replacing the bumper cover, radiator support, hood latch, and headlamps, followed by a realignment of the hood and fender gaps and a refinish of the front end. The labor hours requested match what this kind of work normally takes. The invoices submitted show each part and operation billed once, with no repeated charges.