Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-121564
Estimate date:	7-15-24
Customer:	Chase Bowers
Phone:	832-555-7128
Insurance claim:	C-1250
Vehicle:	2015 Jeep Cherokee
VIN:	MADV7210XCL5Y9596
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$618.27
Left quarter panel	1	$551.34
Left front fender	1	$503.73
Body labor	18.8 hrs	$1,278.79
Paint and materials		$579.94
TOTAL		$3,532.07

Appraiser remarks

The front bumper cover is cracked across the center and the upper grille bracket has snapped. The hood shows a shallow crease toward the drvier side, and the radiator support has a slight bend that will need a sectioned replacement rather than a straight pull. The headlamp assembly on the driver side is cracked but the housing remains intact. Most of the damage lines up well with the reported impact, and the labor hours on the estimate fit the scope of this work. Nothing on the vehicle suggests earlier damage, and the parts and cahrges on the invoices show no repeated entries. The plan is to replace the bumper cover, grille bracket, hood, and headlamp, section and align the radiator support, and then complete a full cooling system pressure test before release.