Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-909095
Estimate date:	4-14-23
Customer:	Ashley Smith
Phone:	713-555-0730
Insurance claim:	C-1253
Vehicle:	2011 Honda Civic
VIN:	5PWX17K687R0D1158
License plate:	428 HT1

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,102.47
Left quarter panel	1	$832.31
Front bumper cover	1	$856.22
Body labor	34.4 hrs	$2,338.21
Paint and materials		$1,455.14
TOTAL		$6,584.35

Appraiser remarks

Inspection of the driver-side door, rear qurater panel and rear wheel arch shows crushing and deep creasing consistent with a side impact at a right-angle intersection. The pattern of deformation lines up with the account given of how the collision occurred. A few shallow scratches near the lower sill appear weathered and may predate this loss, so they have been noted separately and excluded from the scope. The proposed repair plan covers replacing the rear door, straightening the quarter panel, refinishing the affected panels and recalibrating the side sensor. Labor hours requested are in line with the extent of the damage. Line items on the invoice are single entries with no duplicated charges, and the plan is recommended for approval.