Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-373117
Estimate date:	2-15-23
Customer:	Marcus Davidson
Phone:	346-555-8294
Insurance claim:	C-1254
Vehicle:	2022 Kia Sorento
VIN:	
License plate:	245 SPZ

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,327.87
Hood panel	1	$1,172.97
Right front door shell	1	$1,123.14
Body labor	30.2 hrs	$2,055.87
Paint and materials		$988.95
TOTAL		$6,668.80

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp housing is broken, with scuffing and paint transfer on the lower panel. These marks line up with the low-speed contact described in the claim. The repair plan calls for replacing the bumper cover and tail lamp assembly, refinishing the adjacent quarter panel, and recalibrating the parking sensors. Labor time is consistent with the extent of the damage. The invoices provided show no duplicate line items or repeated charges. No prior damage to this vehicle is on record, so the repairs described are limited to this incident.