Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-565128
Estimate date:	2025-01-31
Customer:	Erin Flores
Phone:	281-555-1828
Insurance claim:	C-1255
Vehicle:	2020 Hyundai Elantra
VIN:	DNZ64NHB0DUHC5627
License plate:	2G-DNCY

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$949.33
Hood panel	1	$808.89
Left quarter panel	1	$848.16
Body labor	31.5 hrs	$2,145.26
Paint and materials		$1,199.49
TOTAL		$5,951.13

Appraiser remarks

The vehicle presents with damage to the rear bumper cover, the left quarter panel and the tail lamp assembly, consistent with the low-speed contact reported at the scene. The pattern of crush and paint transfer lines up well with the impact described. Labor hours in this estimate match the extent of the work needed to restore the panels, and no prior damage to the vehicle is known to us. Two similar line items billed on the same date are currently being reviewed and will be confirmed before final approval. Repair plan: replace the bumper cover, repair and refinish the quarter panel, and install a new tail lamp assembly, followed by a road test and final inspection.