Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-231524
Estimate date:	3-10-23
Customer:	Dawn Sims
Phone:	281-555-8397
Insurance claim:	C-1256
Vehicle:	2018 Nissan Altima
VIN:	KC21WJMV7JTN77741
License plate:	6D 33253

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$557.10
Rear bumper cover	1	$543.99
Rear body panel	1	$468.36
Body labor	21.7 hrs	$1,039.63
Paint and materials		$421.16
TOTAL		$3,030.24

Appraiser remarks

The rear bumper cover is cracked and the trunk lid edge is bent, with the taillight assembly broken on the driver side. These marks line up well with the rear-end impact described. The bills show no repeated charges, and no earlier damage to the vehicle is known. The plan is to replace the bumper cover, straighten the lid, and fit a new taillight assembly. The labor hours look a little high for this scope, so I have asked the shop to review the time allowed for the panel work before final approval.