Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-285914
Estimate date:	13 Jul 2023
Customer:	Denise Turner
Phone:	346-555-6351
Insurance claim:	C-1259
Vehicle:	2020 Jeep Cherokee
VIN:	4KLDUVS50YR082976
License plate:	

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,047.14
Right front door shell	1	$893.57
Hood panel	1	$729.26
Body labor	38.2 hrs	$2,595.11
Paint and materials		$1,441.61
TOTAL		$6,706.69

Appraiser remarks

The vehicle shows front-end damage consistent with a low-speed head-on impact, including a cracked bumper cover, a bent upper radiator support, and a damaged hood latch and headlamp bracket. The crush pattern and paint transfer line up with the reported collision, and no prior damage to this vehicle is known. The repair plan calls for replacing the bumper cover, hood latch, and headlamp bracket, straightening the radiator support, and refinishing the affected panels. The labor hours requested fit the scope of this work, and the invoices reviewed show no repeated charges for the same operations. Recommend approval of the repair as written.