Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-281392
Estimate date:	05/19/2023
Customer:	Michele Ramirez
Phone:	281-555-2896
Insurance claim:	C-1260
Vehicle:	2011 Jeep Cherokee
VIN:	M2YTF6E05R6TL4049
License plate:	71M MF4

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$533.60
Rear bumper reinforcement	1	$714.15
Rear body panel	1	$399.28
Body labor	20.4 hrs	$1,384.78
Paint and materials		$629.11
TOTAL		$3,660.92

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease running across its upper edge, with the tail lamp assembly broken on the driver side. The bent reinforcement bar and damaged quarter panel match the force of a rear-end impact described in the claim. Repair will involve replacing the bumper cover and tail lamp, straightening the trunk lid, and refinishing the affected panels. The labor hours requested fit the extent of the damage, and the parts list and invoices show no duplicated charges. Nothing on the vehicle suggests earlier damage to these areas, and the repair plan is recommended as submitted.