Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-648403
Estimate date:	1-20-24
Customer:	Matthew Hardy
Phone:	281-555-4108
Insurance claim:	C-1262
Vehicle:	2020 Toyota Camry
VIN:	X5440GLU3FRXF4179
License plate:	3-93383

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$898.09
Left quarter panel	1	$1,108.28
Hood panel	1	$514.76
Body labor	30.1 hrs	$2,049.17
Paint and materials		$949.60
TOTAL		$5,519.90

Appraiser remarks

Rear quarter panel and bumper cover on the driver's side show crushed metal and a cracked lamp housing, which is consistent with the impact described by the insured while turning left across the path of another vehicle. The pattern of deformation runs in the direction the account suggests, and nothing observed points to older damage on this vehicle. Repair plan calls for replacing the bumper cover, straightening the quarter panel, and installing a new lamp assembly, with labor hours that align with the scope of the work. The shop's invoice lines show each operation billed once, with no duplicate entries.