Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-889300
Estimate date:	2023-06-29
Customer:	Katie Reese
Phone:	832-555-7018
Insurance claim:	C-1263
Vehicle:	2018 Ford F-150
VIN:	GWSDNX0S3W9KE8500
License plate:	W80 0WL

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,416.16
Hood panel	1	$788.79
Headlamp assembly	1	$963.30
Body labor	40.3 hrs	$1,932.17
Paint and materials		$1,402.04
TOTAL		$6,502.46

Appraiser remarks

The rear quarter panel and bumper cover show the main damage, and most of it lines up with a side-swipe impact at a left turn. The left rear door has creased areas that will need straightening and refinishing, and the tail lamp housing is cracked. We found no sign of earlier damage on the vehicle. Two similar charges entered on the same day are still being verified with the shop. The labor hours look slightly high for the work described, so we are asking the shop to review them before approval. Repair plan: replace the bumper cover, repair and repaint the quarter panel, and replace the lamp housing.