Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-993509
Estimate date:	4-23-23
Customer:	Richard Randall
Phone:	281-555-8140
Insurance claim:	C-1264
Vehicle:	2024 Honda Civic
VIN:	U503YM1436NPN0699
License plate:	392-244

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$582.18
Headlamp assembly	1	$689.90
Left front fender	1	$386.01
Body labor	23.1 hrs	$1,567.41
Paint and materials		$683.34
TOTAL		$3,908.84

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with scuffing and paint transfer running along the rear quarter panel. The pattern of the damage lines up well with the low-speed impact that was described, and nothing I found suggests older harm to the vehicle. The repair plan calls for replacing the bumper cover and taillight, refinishing the quarter panel, and recalibrating the parking sensors. The labor hours listed are in line with work of this kind. The invoices submitted contain no duplicate line items or repeated charges, so the estimate can be processed as written.