Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-602890
Estimate date:	July 6, 2023
Customer:	Barbara Tran
Phone:	281-555-0806
Insurance claim:	C-1265
Vehicle:	2021 Ford F-150
VIN:	ZF1BJ4P05LR4C1850
License plate:	SDE U60

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,602.66
Left tail lamp assembly	1	$1,495.52
Rear bumper cover	1	$966.04
Body labor	47.1 hrs	$3,199.64
Paint and materials		$1,316.01
TOTAL		$8,579.87

Appraiser remarks

The rear bumper cover is cracked across the center and the trunk lid shows a crease along its lower edge, consistent with the reported rear-end impact. The tail lamp assembly on the driver side is broken, and the rear quarter panel has a shallow buckle near the bumper mount. No earlier damage to the vehicle is known, and the photos show no signs of prior repair. The labor hours listed fit the scope of this damage. Two similar charges posted on the same day are being verified with the shop before the estimate is finalized. Repair plan: replace the bumper cover, tail lamp, and trunk lid, and repair the quarter panel.