Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-890398
Estimate date:	09/17/2023
Customer:	Joshua Aguirre
Phone:	346-555-5999
Insurance claim:	C-1267
Vehicle:	2013 Honda Civic
VIN:	W631TPT04PJLM6668
License plate:	7U-VMHP

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$663.69
Front bumper cover	1	$342.64
Hood panel	1	$424.32
Body labor	20.8 hrs	$1,000.61
Paint and materials		$505.99
TOTAL		$2,937.25

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support is bent, with the hood latch and both headlamp brackets displaced. The crush pattern and paint transfer on the bumper line up with a frontal strike of this kind, and nothing I found points to older damage on this vehicle. The shop's plan is to replace the bumper cover, radiator support, latch and both brackets, then realign and refinish the front end. The labor horus on the estimate run a bit above what I would expect for this scope, so I have asked the shop to justify several line items before final approval. The invoices submitted so far do not show any duplicate charges.