Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-636692
Estimate date:	06/21/2024
Customer:	Sean Faulkner
Phone:	346-555-1470
Insurance claim:	C-1268
Vehicle:	2010 Ford F-150
VIN:	ANMHC8DL7VKVH7408
License plate:	72-GT96

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$625.35
Hood panel	1	$508.76
Front bumper cover	1	$374.60
Body labor	14.3 hrs	$970.02
Paint and materials		$419.37
TOTAL		$2,898.10

Appraiser remarks

The front bumper cover is cracked and the grille support has bent inward, with the hood latch and radiator core support showing deformation consistent with a frontal strike. Headlamp assembly and fog lamp housing are broken on the driver side, and the radiator shows minor fin damage without leaks. The damage pattern lines up well with the impact as described. Repair plan calls for replacing the bumper cover, grille, hood latch, and headlamp, straightening the core support, and performing a wheel alignment and sensor recalibration. The labor hours fit the scope of this work. Billing shows no repeated charges, and no proir damage to the vehicle is known.