Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-642732
Estimate date:	12-4-24
Customer:	Ashley Kennedy
Phone:	713-555-5932
Insurance claim:	C-1269
Vehicle:	2019 Chevrolet Malibu
VIN:	CXUH16CH711Y81781
License plate:	451 PUD

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$324.00
Right front door shell	1	$217.60
Headlamp assembly	1	$147.45
Body labor	8.6 hrs	$414.80
Paint and materials		$284.72
TOTAL		$1,388.57

Appraiser remarks

The vehicle shows a crushed and creased left front fender, a cracked headlamp assembly, and a bent front bumper bracket on the driver side. The impact pattern is consistent with a vehicle turning left into the path of another car. Some of the lower bumper scuffing and the inner wheel well damage may not be clearly tied to this event, so those items need closer inspection before final approval. The repair plan calls for replacing the fender and headlamp, straightening the bracket, and refinishing the affected panels. The labor hours requested are a little high for this scope of work and should be reviewed against standard repair times. No earlier damage to the vehicle is known, and the shop invoices show no repeated charges.