Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-214698
Estimate date:	2024-11-20
Customer:	Colleen Jones
Phone:	
Insurance claim:	C-1272
Vehicle:	2011 Kia Sorento
VIN:	C9P0PJD38MB5N9353
License plate:	GVJ-660

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$636.64
Left quarter panel	1	$781.27
Front bumper cover	1	$527.08
Body labor	32.2 hrs	$1,545.02
Paint and materials		$576.41
TOTAL		$4,066.42

Appraiser remarks

The rear passenger door and quarter panel show deformation consistent with a side impact at an intersection, and the crush pattern lines up with the account given of how the collision happened. Parts invoices and shop billing reviewed to date show no repeated or duplicate charges. Labor hours on the estimate run somewhat high for the damage visible, so the shop should be asked to justify the time allotted for panel straightening and refinishing. Nothing in the file suggests earlier damage to this vehicle. Recommended plan: replcae the rear door shell, repair the quarter panel, and refinish both panels, subject to a revised labor figure.