Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-184881
Estimate date:	01/06/2025
Customer:	Scott Perry
Phone:	832-555-5213
Insurance claim:	C-1273
Vehicle:	2010 Kia Sorento
VIN:	AR1BDMUJ7UZ6P0930
License plate:	796-WRN

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,317.64
Rear body panel	1	$1,490.17
Rear bumper reinforcement	1	$1,327.15
Body labor	40.8 hrs	$2,771.91
Paint and materials		$1,222.08
TOTAL		$8,128.95

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a crease running toward the wheel well, which lines up well with the reported rear-end impact. The tail lamp assembly is broken and the trunk lid edge is bent. Repair planned: replace the bumper cover and tail lamp, pull and refinish the quarter panel, and realign the trunk lid. The labor hours requested match the scope of this damage. No prior damage to this vehicle is on record, and the parts and labor charges on the invoices show no repeated entries.