Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-528861
Estimate date:	7 Mar 2024
Customer:	Kevin Walker
Phone:	713-555-6260
Insurance claim:	C-1274
Vehicle:	2015 Ford F-150
VIN:	7ANU3U91X3H489818
License plate:	Z14 0JX

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,368.81
Headlamp assembly	1	$1,005.81
Front bumper cover	1	$1,311.03
Body labor	63.1 hrs	$3,028.93
Paint and materials		$1,503.39
TOTAL		$8,217.97

Appraiser remarks

The front bumper cover is cracked acrsos the center and the upper radiator support is bent, with the hood latch and both headlamp assemblies damaged. The fracture pattern and crush depth line up well with the reported head-on impact, and no prior damage is known on this vehicle. The plan is to replace the bumper cover, radiator support, hood latch and headlamps, then realign the cooling package and run a full scan for sensor faults. The labor hours on the estimate look a little high for this scope, so the shop should justify them line by line. Two similar charges posted on the same day are also being checked against the invoice before approval.