Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-344621
Estimate date:	6-24-24
Customer:	Alexander Cooper
Phone:	281-555-6565
Insurance claim:	C-1275
Vehicle:	2017 Chevrolet Malibu
VIN:	8V49NDFY5R4KF9708
License plate:	5-8725P

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,340.12
Right front door shell	1	$1,710.10
Headlamp assembly	1	$892.08
Body labor	45.2 hrs	$3,071.61
Paint and materials		$1,442.79
TOTAL		$8,456.70

Appraiser remarks

The right rear quarter panel and rear passenger door show scraping and creasing along their lower edges, with paint trnasfer and a cracked side marker lens. The damage pattern lines up with the reported sideswipe during a lane change, and the vehicle shows no sign of older impact damage in the same area. Repairs call for replacing the marker lens, blending the paint on the quarter panel, and straightening and refinishing the door skin. The labor hours on the estimate are consistent with the work described, and the parts and charges listed appear only once with no duplicate entries. Recommend approval of the repair as written.