# Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-620807 |
| **Estimate date:** | January 12, 2025 |
| **Customer:** | Tracey Guzman |
| **Phone:** | 281-555-7657 |
| **Insurance claim:** | C-1278 |
| **Vehicle:** | 2010 Jeep Cherokee |
| **VIN:** | HC2S02R528ZV04849 |
| **License plate:** | KSQ 113 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Front bumper cover | 1 | $949.88 |
| Hood panel | 1 | $855.54 |
| Left front fender | 1 | $742.18 |
| Body labor | 33.0 hrs | $1,584.07 |
| Paint and materials | | $1,053.79 |
| TOTAL | | $5,185.46 |

### Appraiser remarks

The vehicle shows a side impact to the driver's rear quarter panel, with a crushed rear door, a cracked taillight lens, and scuffing along the rocker panel. Some of the lower body damage may not be from this collision, and the shop should confirm that before repair begins. The billing shows no repeated charges. The labor hours are slightly high for the damage described, so a review of the time allowances is recommended. No prior damage to this vehicle is known. The plan is to replace the rear door shell, refinish the affected panels, and install a new taillight assembly, with the rocker panel repaired only if the teardown confirms it was damaged in this loss.