Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-244842
Estimate date:	03/26/2024
Customer:	Victoria Jenkins
Phone:	
Insurance claim:	C-1279
Vehicle:	2023 Hyundai Elantra
VIN:	6UELY58TXZHX74466
License plate:	MFV 901

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$538.04
Hood panel	1	$583.43
Headlamp assembly	1	$532.96
Body labor	16.6 hrs	$1,128.60
Paint and materials		$472.17
TOTAL		$3,255.20

Appraiser remarks

The front bumper cover is cracked and displaced, the grille support has separtaed on the driver side, and the hood latch and radiator support show deformation consistent with a frontal impact at low speed. Some of the lower crossmember damage may have come from this event, but it is not clear whether all of it did, so that area has been flagged for closer review. The proposed repair plan replaces the bumper cover, grille support, and hood latch, and straightens the radiator support. The labor hours listed fit the damage described. The shop's invoices show no repeated charges for the same work. No earlier damage to this vehicle is known.