Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-414123
Estimate date:	10 May 2024
Customer:	Kathryn Edwards
Phone:	832-555-7574
Insurance claim:	C-1280
Vehicle:	2018 Kia Sorento
VIN:	R5X1R7RSX92Y98464
License plate:	818 YQC

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$581.15
Hood panel	1	$426.41
Left front fender	1	$505.68
Body labor	13.8 hrs	$939.58
Paint and materials		$640.51
TOTAL		$3,093.33

Appraiser remarks

The left rear quarter panel and rear door show scrpae marks, a cracked taillight lens, and a dented fender lip that line up with a sideswipe during a lane change. The damage pattern is consistent with the impact described. A few older scratches are also visible on the lower door, and these may predate this incident, so they have been noted separately and are not included in the repair scope. The proposed plan covers panel repair, refinishing the affected area, replacing the lamp assembly, and a short run of blending to match paint. Labor hours are in line with the work described. The invoices reviewed show no repeated charges for the same operations. Final approval is subject to a teardown inspection once the bumper cover is removed.