Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-909844
Estimate date:	10/18/2023
Customer:	George Booker
Phone:	832-555-0676
Insurance claim:	C-1282
Vehicle:	2014 Jeep Cherokee
VIN:	LBTKBR7N96G794897
License plate:	7705 FZ

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,299.50
Left front fender	1	$1,554.27
Front bumper cover	1	$1,430.36
Body labor	51.8 hrs	$2,485.24
Paint and materials		$1,333.96
TOTAL		$8,103.33

Appraiser remarks

The rear bumper cover shows a deep crease with cracked mounting tabs on the driver side, and the left taillight assembly is broken at its housing. Paint transfer and scuffing line up with the reported impact, and the damage pattern is consistent with the account given. Nothing in the file suggests earlier damage to this vehicle. The repair plan calls for replacing the bumper cover, the taillight assembly, and the associated brackets, followed by refinishing. The invoiced items show no repeated charges. Labor hours appear slightly high for this scope, so the shop should justify each line before approval.