Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-973488
Estimate date:	February 21, 2024
Customer:	James Obrien
Phone:	832-555-1722
Insurance claim:	C-1284
Vehicle:	2012 Jeep Cherokee
VIN:	VNXJUNMV8P6BH8564
License plate:	46-SH82

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,898.24
Left tail lamp assembly	1	$1,088.44
Rear bumper cover	1	$1,180.58
Body labor	71.3 hrs	$3,420.59
Paint and materials		$1,439.50
TOTAL		$9,027.35

Appraiser remarks

The rear bumper cover is cracked across the center, with the left quarter panel and tail lihgt assembly crushed inward. These injuries line up well with the rear-end impact described. Nothing in the file points to earlier damage on this vehicle. The proposed plan replaces the bumper cover and tail light, repairs and refinishes the quarter panel, and checks the trunk floor for hidden deformation. The labor hours run a little high for this scope, so I recommend a second review of the time allowances before approval. The billing shows no repeated charges.